

CANBY

Doing Your Homework
Gathering Information Before You Start

What Do You Know?

Canby Grove Conference Center
<http://www.csrnet.org/canbygrove>
7501 Knights Bridge Road
Canby OR 97013

Molalla River State Park

Pudding River

What Can You Find?

Yahoo Maps

Black & White Aerials and Topos
<http://terraserver.microsoft.com>
Canby Grove.jpg

Canby, OR

Canby Telecommunications Center, Clackamas County
<http://www.ci.canby.or.us>
City of Canby
Current Zoning Map
Comprehensive Plan Zoning Map

NO GIS

Clackamas County Community College
28,000 headcount, 8,000FTE, no Environmental Science, no GIS Distance Learning
NO GIS

Clackamas County GIS

<http://www.co.clackamas.or.us/gis>
Aerial photos (orthophotos \$45/sq ml), Watersheds (Molalla) jpeg, Rainfall jpeg
CMAP – not user friendly, not downloadable; zoomable DEM, Fire, School, and Park
Districts, Soils, Flood zones, tax lots.

RLIS (Regional Land Information System). **Digital data for sale METRO.**

<http://www.metro-region.org>
METRO Map (parcels, text; GIS data/maps&data library/free aerial photos)

Oregon GIS

<http://www.gis.state.or.us/links.html>

Season	Winter/Spring/Fall
Listing Status	303(d) List
Supporting Data	DEQ Data (2 sites: 402314, 402029; RM 2.5, 3.5): 21% (3 of 14), 11% (4 of 37) FWS values respectively exceeded fecal coliform standard (400) with maximum values of 1100, 1100 between WY 1986-1995.

Pudding River

303(d) Listed for Fecal Coliform (Winter/Spring/Summer/Fall)

Supporting Data: DEQ Data (4 sites: 402594,404207,402317,402319: RM 8.1 – 26.9): Exceeded fecal coliform standard (400) with maximum values of 2400, 1600, 1600, 1600 respectively between WY 86-95. Summer maximum values of 460, 460, 460, 1100 respectively between 1987-95.

Also listed for Temperature (salmon rearing, 17.8 C) exceedances each year 86-95.

Also listed for DDT at Aurora site 14202000: 2 of 4 values at or above detection, with an average of 0.0015 ug/l exceeded DDDT standard (0.001 ug/l – fresh water chronic criteria) between 5/25 – 11/9/94.